



GARY R. HERBERT
Governor
GREGORY S. BELL
Lieutenant Governor

State of Utah


DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program July 3, 2013

Reviewed: 

Mine Name: Eagle Canyon Quarry	Permit Number: M/015/0050
Operator Name: Georgia Pacific Corporation	Inspection Date: July 1, 2013
Inspector(s): Wayne Western	Time: 1:30 – 2:00 pm
Other Participants: none	Mine Status: INA
Weather Condition: 90's and partly cloudy	Last Inspection: July 7, 2013
Bond Renewal Date: 2008 – partial bond release granted	Bond Amount: \$73,000.00
Surface Ownership: BLM	Mineral Ownership: BLM
Last Year of Production: 2008	Acreage: 45 acres

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer,	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Bond/Bond Release	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Annual Fees	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Annual Report	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This was a routine inspection.

Inspection Summary:

The site was reclaimed in 2008 and given partial bond release.
The bond on the site is adequate to reseed in the event of vegetation failure.
The site was regrading and there are no signs of instability.

Conclusions and Recommendations:

The Division should continue to monitor the site.

The Division should have a biologist evaluate the site and make recommendations to the Operator about what is needed to get the site ready for final bond release.

Directions to Site:

Inspector's Signature _____

WHW:

cc: (OPERATOR)

ggochnour@blm.gov

O:\M015-Emery\M0150050-EagleCanyonQuarry\inspection\INSP-07012013.doc




Reclaimed area.



Reclaimed area note regarding efforts.



Reclaimed area with undisturbed area in background.



Undisturbed area across the road